



Diagram illustrating the assembly of a three-drawer unit. The components are labeled with their respective part numbers and quantities:

#	ART. NR	X
1	401	1
2	402	1
3	101	1
4	102	1
5	701	4
6	301	8
7	305	4
8	050	4
9	001	2
10	350	2





The diagram also shows the dimensions of the unit: 90 cm height, 43 cm width, and 90 cm depth. A small illustration shows the unit being assembled, with a smiley face indicating the correct assembly path and a frowny face indicating the incorrect path.

A horizontal ruler with a scale from 0 to 6 centimeters. Major tick marks are labeled at 0, 1, 2, 3, 4, 5, and 6. Minor tick marks are present every millimeter. A grey arrow points to the 4.5 cm mark, which is halfway between 4 and 5.





1






2








3







4



5



6



7

